

3000 series insert packing instructions - pack in this sequence. **IT IS IMPERATIVE THAT THE INSERT BE UPSIDE DOWN**



4/5000 series insert packing instructions - pack in this sequence (note that 5500 series inserts will not have any packaging on the bottom) **DO NOT TURN THE INSERT UPSIDE DOWN**

